## Commonwealth of Massachusetts Executive Office of Environmental Affairs ■ MEPA Office

## **ENF**

Revised 10/99

## **Environmental Notification Form**

For Office Use Only Executive Office of Environmental Affairs

EOEA No.: 13596 MEPA AnalystBill GAGE

Phone: 617-626-1025

The information requested on this form must be completed to begin MEPA Review in accordance with the provisions of the Massachusetts Environmental Policy Act, 301 CMR 11.00.

Project Name: Upstream repairs and improve	ements to Bolivar Pond Dam				
Street: Bolivar Street					
Municipality: Canton	Watershed: Neponset River Basin				
Universal Tranverse Mercator Coordinates:	Latitude: 229686				
	Longitude: 877971				
Estimated commencement date: Fall 2005	Estimated completion date: Spring 2006				
Approximate cost: \$300,000	Status of project design: 100 %complete				
Proponent: Department of Public Works					
Street: 801 Washington Street					
Municipality: Canton	State: MA Zip Code: 02021				
Name of Contact Person From Whom Copies of this ENF May Be Obtained: Michael Trotta					
Firm/Agency: Department of Public Works	Street: 801 Washington Street				
Municipality: Canton	State: MA Zip Code: 02021				
Phone: 781-821-5023   Fax: 78	1-821-2871 E-mail:				
Has this project seen filed with MEPA before?  Has any project on this site been filed with MEPA	Yes (EOEA No) \(\sum \text{No}\) \text{No} \text{before?}				
Is this an Expanded ENF (see 301 CMR 11.05(7)) required a Single EIR? (see 301 CMR 11.06(8)) a Special Review Procedure? (see 301 CMR 11.09) a Waiver of mandatory EIR? (see 301 CMR 11.11) a Phase I Waiver? (see 301 CMR 11.11)	Yes (EOEA No)       ☑No         esting:       ☑No         ☐Yes       ☑No         ☐Yes       ☑No         ☐Yes       ☑No				
Identify any financial assistance or land transfer for the agency name and the amount of funding or la	rom an agency of the Commonwealth, including and area (in acres):				
Are you requesting coordinated review with any o					
List Local or Federal Permits and Approvals:					
Con Com Mass Historical Commission					
Which ENF or EIR review threshold(s) does the p	project meet or exceed (see 301 CMR 11.03):				

Comment period is limited. For information call 617-626-1020

Summary of Project Size & Existing & Environmental Impacts  LAND  Total site acreage 0.057Ac  New acres of land altered  Acres of impervious area N/A  Square feet of new bordering	Chang	e Total	State Permits & Approvals Order of Conditions
Total site acreage  New acres of land altered  Acres of impervious area  N/A  Square feet of new bordering	N/A		Order of Conditions
Total site acreage  New acres of land altered  Acres of impervious area  Square feet of new bordering	N/A		
New acres of land altered  Acres of impervious area  Square feet of new bordering	N/A		
Acres of impervious area  N/A  Square feet of new bordering	N/A		Superseding Order of
Square feet of new bordering			Conditions Chapter 91 License
Square feet of new bordering	N/A	N/A	☐ 401 Water Quality
regetated wetlands alteration	0.042Ac		Certification  MHD or MDC Access Permit Water Management Act Permit New Source Approval DEP or MWRA Sewer Connection/ Extension Permit
Square feet of new other wetland alteration	N/A		
Acres of new non-water dependent use of tidelands or waterways	N/A		
STRUCTURES	5		☐ Other Permits
Gross square footage N/A	N/A	N/A	(including Legislative Approvals) – Specify:
Number of housing units N/A	N/A	N/A	Approvais) - Opecity.
Maximum height (in feet) N/A	N/A	N/A	-
TRANSPORTATI	ON 🦠		
Vehicle trips per day N/A	N/A	N/A	
Parking spaces N/A	N/A	N/A	
WATER/WASTEWA	ATER	114	
Gallons/day (GPD) of water use N/A	N/A	N/A	
GPD water withdrawal N/A	N/A	N/A	
GPD wastewater generation/ N/A reatment	N/A	N/A	
ength of water/sewer mains (in miles)	N/A	N/A	

HISTORICAL /ARCHAEOLOGICAL RESOURCES: Does the project site include any structure, site or district listed
in the State Register of Historic Place or the inventory of Historic and Archaeological Assets of the Commonwealth?  See Specify The former Ames Shovel Shop Factory)
If yes, does the project involve any demolition or destruction of any listed or inventoried historic or archaeological resources?
☐Yes (Specify)   ☑No
AREAS OF CRITICAL ENVIRONMENTAL CONCERN: Is the project in or adjacent to an Area of Critical
Environmental Concern?
□Yes (Specify) ⊠No

**PROJECT DESCRIPTION:** The project description should include **(a)** a description of the project site, **(b)** a description of both on-site and off-site alternatives and the impacts associated with each alternative, and **(c)** potential on-site and off-site mitigation measures for each alternative (*You may attach one additional page, if necessary.*)

In January of 2004 a portion of the existing wall along the upstream dam face of Bolivar Pond dam collapsed into Bolivar Pond. The Town was issued an order on March 12, 2004 by the Office of the dam Safety, a division of the Massachusetts Department of Conservation and Recreation to repair the dam.

The proposed work involves repairs and modifications to the upstream face of the dam, a main spillway about 200 ft. east of the main dam and an emergency dam located about 150 ft. southeast of the spillway. The dam is a retained by an earth/rockfill embankment. The upstream side of the embankment is mostly retained by an old stone masonry wall, a portion of which has failed. The down stream embankment face is mostly retained by the wall of a historic building – the former Ames Shovel Shop Factory. The dam spillway originally consisted of a twin gated (two weirs comprised of changeable wooden boards) concrete/rock raceway The weir structure was temporarily removed in the Spring of 2004. The emergency spillway consists of an approximately 30" PVC pipe in an uncovered drywell or manhole located on the Town beach/recreation land.

This proposed project involves work in 3 different locations. Work is shown on a set of plans included with this ENF prepared by Stevens Associates dated 7/7/2005

Area 1 involves repairs to the upstream wall of the dam which involves reconstruction of a small area of roadway, sidewalk and curb. The section of the stone parapet that has failed will be reconstructed along with new filling and grading. See Sheet 3 of 8 for the details.

Area 2 involves repairing the outlet and installation of a flash rack and flash boards. There will also be grading and rip-rap done to the auxiliary outlet. See Sheet 6 of 8 and part of Sheet 7 of 8 foe details.

Area 3 involves the installation of flash rack and flash boards to the spillway. See part of Sheet 7 of 8 for details.